

3.3.2A

29.12.23: - keep active sheet on Update_All_Start_LedNr function exit
18.01.24: - new function SafeChDriveAndDir with Additional check for network drives (#11425)
19.01.24: - improved selection of old prog generator filename when updating to new release/beta
- add experimental support of LNet for ESP32
20.01.24: - fix LastFilledRowIn_ChkAll
- fix detection of first RGB_Heartbeat line while import
- change release to beta 3.3.2A

3.2.1A

04.11.22 fix SwitchC issue with ESP32

3.2.1B

20.12.22 add missing code for old "slow" build
21.12.22 fix issue that AVR build fails caused by vbcr in LEDs_Autoprog.h
-> replace by vbcrLf

3.2.1C

21.12.22 add missing macros InCh_to_LocalVar, InCh_to_LocalVar1 and Bin_InCh_to_TmpVar1 to sheet Lib_Macros
05.01.23 Store_Status: support SwitchB, extend max. InCnt to 63, check max InCnt, use Set_Input for SwitchB
14.01.23 Add macro SingleLedSignal and SingleLedSignalEx

3.2.1D

10.03.23 Support of new input type "feedback"
10.03.23 process CAN messages from ATTiny_CAN_GBM module
10.03.23 new macro include to include excel sub sheets
10.03.23 experimental support of ProgGenerator stored in a Onedrive folder
21.03.23 if SEND_INPUT is enabled also SwitchA, SwitchD and Variable changes are notified
09.04.23 GEN_BUTTON_RELEASE mode are now settable in config sheet
18.04.23 Finalize include sheet feature
26.05.23 fix issue that AVR build fails caused by vbcr in LEDs_Autoprog.h
-> replace by vbcrLf

3.2.1E

18.05.23: - LNet support for Arduino platform added
13.09.23: - Hardi: Merged Hardis changes for the Word Clock
Added OutCnt to the MLL Extensions

Don't generate warning if "Pattern" macro is found
Added define COPYLED_OFF and COPYLED_OFF_ONCE

3.2.1F

15.09.23: - New Macro Set_LEDNr added
18.09.23: - New Macro CopyNLEDs added
20.10.23: - Juergen: fix #10763
23.10.23: - Juergen: revert one of Hardis changes - fixes problem #10 reported by Nessie

3.2.1H

29.11.23: - Hardi: New Icons from Michael

3.2.1I

30.11.23: - Hardi: Added Juergens changes again

3.2.1J

04.11.23: - Juergen: fix #10159 - fastbuild.cmd has wrong Unix line ending
04.12.23: - Juergen ensure that included sheet uses same protocol as the main sheet
09.12.23: - Juergen add experimental support of ATmega328PB
 - enable bootloader update without need to set jumpers
(Mainboard version >= 1.8.2)

From:

<https://wiki.mobaledlib.de/> - MobaLedLib Wiki

Permanent link:

<https://wiki.mobaledlib.de/spezial/betaversion?rev=1705774927>

Last update: **2024/01/20 19:22**

